

## OPTIONAL ACCESSORIES

### PLS-5219GDSK

Ground disk to buss together the six ground contacts (solder connectors only)



### PLS-5219 CBGD/PG29

Strain Relief directly coupling into thread housing



### M2250/1-01 Crimp Tool



**PLS-5219CPM** Crimp Male Contact

**PLS-5219CPFE** Crimp Female Earth Contact

**PLS-5219CPF** Crimp Female Contact

